# Oil Field Environmental Incident Summary

Responsible Party: HUNT OIL COMPANY
Well Operator: HUNT OIL COMPANY
Well Name: SMOKY BUTTE 160-100-18-19H-1

Field Name: SMOKY BUTTE Well File #: 28748

Date Incident:11/20/2014Time Incident:10:00Facility ID Number:County:DIVIDETwp:160Rng:100Sec:18Qtr:

Location Description:

Submitted By: Daniel Mosher Received By:

Contact Person: Daniel Mosher

1900 NORTH AKARD STREET DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil

Brine 2 Barrels 2 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/22/2015 Clean Up Concluded: 12/12/2014

#### Risk Evaluation:

No immediate risk, Called and dispatched JMAC Spill response team to initiate clean up of contaminated soil on location

#### Areal Extent:

# Potential Environmental Impacts:

No likelihood of impacting soil or water nearby. Spill is small enough that it is completely contained and will be reclaimed within 24hrs.

## Action Taken or Planned:

Scoria on location absorbed fluid and stopped spreading. Organized traffic on location to go around area. JMAC Dispatched to cleanup

Wastes Disposal Location: Indian Hills Disposal (owned by JMAC)

Agencies Involved:

## **Updates**

Date: 11/21/2014 Status: Reviewed - Assigned to Other Agency Author: Espe, Brady

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to truck overflow, remained on location according to the report. NDIC retains oversight.